

S		
	HIDE	>
		J

XTREME	Standard	Result
Tensile test	DIN EN ISO 1421	Excellent
Tear propagation strength	DIN 53356 in Newton	Excellent
Flex resistance behaviour	DIN 53351 30,000 flex operations	Without changes
Cold crack resistance at -10°C	DIN EN 1876-1	Passed
Sweat fastness	DIN EN ISO 105-E04	Excellent (maximum marks)
Seawater fastness	DIN EN ISO 105-E02	Excellent (maximum marks)
Rub fastness	DIN EN ISO 105-X12	Excellent (maximum marks)
Martindale rub resistance	DIN EN ISO 5470-2	Excellent
Light fastness	DIN EN ISO 105-B02	Excellent
Soiling behaviour	ISO 26082	Excellent
Water/alcohol droplet test		Excellent (maximum marks)
Oil repellence test		Excellent (maximum marks)
Adhesion	IUF 470/ISO 11644	> 2.5 N/10mm
Antibacterial > 99.9%		Excellent
Low flammability	DIN EN 1021 part 1 + 2; ISO 8191-1; BS 5852 source 3; California TB 117 (Draft 02/2002).	
Certificates can be provided on request.		

XTREME LEATHER

XTREME - the unique innovation in leather by Boxmark. An extremely hard wearing leather, which combines high technical qualities with captivating and ensuring sensations of real leather.

XTREME is suitable for various environments:

Outdoor	Marine	Automotive after sales
Contract	Aviation	Coaches
Medical, Fitness & Spa	Railway	

XTREME Characteristics

Antibacterial, antimicrobial, mildew resistant, oil, water, alcohol and soil resistant, sweat resistant, easy to clean, disinfection agent resistant (according to summary on www.boxmark.com), lightfast, highly abrasion resistant, highly stretch and tear resistant, saltwater resistant, flame resistant, break resistant even at freezing temperatures. IMO and other norms on request.

Leather Description

- Top grain leather, thickness 1.3 1.4mm
- Natural enhanced grain
- Raw product: Central European heavy bull hide, average size 5.3m²
- Tanning: strong vegetable re-tanned, chrome leather
- Natural features are visible
- Slight shine, colour and structure differences are normal
- Patina and shiny spots during use are typical of the product
- · XTREME complies with regulations for freedom from harmful substances
- XTREME is easy to maintain, however, it should be cared for and cleaned with the XTREME cleaning system
- XTREME is only authentic with the recurring Boxmark X on the reverse side of the leather.

Service Instructions

- XTREME needs no special care
- Every 3 months use the XTREME Cleaning System in accordance with instructions
- · Clean dust off the leather frequently with a soft, dry woollen cloth using light circular movements, or use a vacuum cleaner
- If the leather does get dirty, never rub hard, but carefully remove the dirt towards the centre of the spot. Use the XTREME Cleaning System to clean a large area.
- If the XTREME Cleaning System no longer helps for specific, heavy staining, contact us, and we will recommend a leather cleaning company
- Never use chemicals, household cleaners or other aggressive cleaners. They will damage the leather.
- For allowed disinfecting agents please see the manufacturer's website: www.boxmark.com